






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD...


Position

- 1 = A 961 449 XX
- 2 = A 961 456 XX
- 3 = A 961 950 NU
- 4 = E 960 575 NU
- 5 = E 960 664 NU
- 7 = B 960 568 XX
- 9 = A 860 415 NU
- 11 = A 961 810 NU (2x)
- 12 = A 961 139 NU (2x)
- 13 = A 960 599 XX
- 14 = A 961 893 XX
- 16 = A 961 927 XX







CERAPLUS
 A 4162 ..

1108 / A 865 719
 (+ A 865 612)
 Made in Germany



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P	bar		MAX. 5		3		Q	(3 bar)
	T	°C		MAX. 80		65			l/min
						40			23

