





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX= AA,AD,..


Position

- 1 = A 962 052 XX
2 = A 962 053 XX
3 = A 960 396 XX
4 = A 961 268 NU (2x)
5 = A 960 445 NU
6 = A 961 864 XX
7 = A 962 574 NU
8 = A 962 335 NU
9 = A 960 462 NU
12 = A 961 010 NU
13 = A 963 026 NU
15 = A 960 113 XX
16 = A 960 111 AT
17 = A 962 227 XX
18 = A 961 807 NU
20 = A 961 798 NU
21 = A 960 110 XX
23 = A 961 811 NU
24 = A 961 810 NU
26 = A 961 816 NU
27 = A 963 028 NU
28 = A 963 030 NU
29 = A 963 090 NU
31 = A 961 817 NU (5x)
32 = H 960 184 NU
A 962 594 NU (2x)
33 = H 960 185 NU
34 = H 960 440 XX
35 = A 962 061 XX
36 = A 960 239 NU
37 = B 960 578 XX




MELANGE
A 4335 ..


0811 / A 865 876
(+ A 865 612)
Made in Germany



Ideal Standard International BVBA
Chaussée de Wavre, 1789 - box 15
1160 Bruxelles
Belgium

www.idealstandardinternational.com





	P	bar			 Q (3 bar)
	T	°C			