





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Reservju daļu



XX = AA, AD...





Position

1 = A 962 872 XX	12 = A 962 568 NU
3 = A 962 870 XX	14 = A 962 529 NU
4 = A 962 998 NU	15 = A 961 332 NU
5 = A 962 871 XX	18 = A 962 594 NU
6 = A 963 427 NU	19 = A 961 810 NU
7 = A 962 229 NU	20 = A 962 595 NU
8 = A 962 230 NU	21 = E 960 440 XX
9 = A 963 432 NU	22 = A 963 651 NU
10 = A 962 563 NU	23 = A 960 395 NU




CERATHERM 100
 A 4815 .. A 4816 ..





0812 / A 866 266
 (+ A 865 612)
 Made in Germany






Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





	P	bar	MIN. 0.1	MAX. 5		Q (0.2 bar)
	T	$^{\circ}\text{C}$	MAX. 80	65 55		l/min 4.7



A962568NU