



Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu





XX = AA, GN, ...

Pos.	Part No.
1	A 861 405 XX
2	A 963 309 NU
3	A 861 406 NU
4	B 961 373 XX
5	B 961 374 NU
6	B 960 650 NU
7	A 861 181 NU
8	A 861 156 NU
11	A 961 810 NU
12	A 963 651 NU
13	A 962 594 NU
16	A 961 182 NU
17	A 961 139 NU
19	B 960 365 AA
20	A 963 840 NU
21	B 960 647 AA
22	A 962 077 XX


A 7032 AA

A 7032 AA

A 7032 XX



P	50°C	15°C	0	1	2	3	4	5
			°C	°C	°C	°C	°C	°C
0,3 MPa	65°C	15°C	50	49	44	40	35	33
3 bar	85°C	15°C	65	63	57	50	44	40
			85	83	74	64	56	50






CONNECT AIR
A 7032 ..




Ideal Standard






0520 / A 868 371
Made in Germany



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





	P	bar				Q (3 bar)
	T	°C				
						l/min 24

