




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD...

Position


- 1 A 960 887 XX
- 2 A 963 309 NU
- 3 A 963 877 NU
- 4 A 960 363 XX
- 5 A 961 667 NU
- 7 A 962 715 NU
- 8 A 963 372 NU
- 9 A 962 716 NU
- 11 A 963 981 NU
- 13 A 962 857 NU
- 14 A 960 642 NU
- 16 A 961 623 NU
- 19 A 960 071 NU
- 20 A 962 160 NU
- 22 A 963 754 NU
- 24 A 961 810 NU
- 25 A 963 651 NU
- 26 A 962 594 NU
- 27 A 960 025 NU
- 30 A 961 076 NU
- 31 A 961 077 XX
- 32 A 960 483 XX
- 33 A 961 328 NU
- 34 A 963 287 XX
- 35 A 960 026 XX
- 36 A 961 078 XX
- 37 A 963 667 NU




## MOMENTS

A 3910 .. A 3914 ..


0413 / A 865 571 40  
 (+ A 865 612)  
 Made in Germany



A 3910



A 3914



Ideal Standard International BVBA  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium

www.idealstandardinternational.com



