




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu





- 1 A 962 872 AA
- 2 A 962 998 NU
- 3 A 962 950 AA
- 5 A 963 432 NU
- 6 A 963 286 AA
- 7 A 963 249 AA
- 8 A 963 177 NU
- 9 A 963 246 NU
- 10 A 963 247 NU
- 11 A 961 214 NU
- 12 A 963 284 NU
- 13 A 961 640 NU
- 16 A 963 003 NU



## CERATHERM 100

### A 4656 ..

0116 / A 866 249  
(+ A 865 612)  
Made in Germany



Ideal Standard International NV  
Corporate Village - Gent Building  
Da Vincilaan 2  
1935 Zaventem  
Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)

