





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Reservju daļu



Position






1 = A 962 872 AA	12 = A 962 568 NU
3 = A 962 870 AA	14 = A 962 529 NU
4 = A 962 998 NU	15 = A 961 332 NU
5 = A 962 871 AA	18 = A 962 594 NU
6 = A 963 427 NU	19 = A 961 810 NU
7 = A 962 229 NU	20 = A 962 595 NU
8 = A 962 230 NU	21 = E 960 440 AA
9 = A 963 432 NU	22 = A 963 651 NU
10 = A 962 563 NU	23 = A 960 395 NU



ideal
STANDARD





CERATHERM 100
A 4815 .. A 4816 ..

0120 / A 866 266
Made in Germany



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com



	P	bar	MIN. 0.5	MAX. 5	 Q (1.0 bar) l/min 11
	T	°C	MAX. 80	65 55	

