






Spare Parts / Ersatzteile / Pièces de rechange / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



XX = AA, AD...




1	A 963 131 NU	23	A 962 481 NU
4	A 963 132 NU	25	A 960 899 NU
8	A 963 143 NU	26	A 962 368 NU
9	A 963 146 NU	27	A 962 384 XX
10	A 963 147 NU	28	A 960 895 NU
13	A 962 594 NU	29	A 962 483 XX
15	A 960 890 NU	30	A 961 659 NU
16	A 960 706 NU	32	A 962 388 XX
17	A 960 891 NU	33	A 962 879 XX
18	A 962 480 NU	35	A 962 878 XX
20	A 963 564 NU	36	A 960 704 NU
21	A 963 427 NU		A 962 476 NU
22	A 962 391 XX	37	A 962 475 XX




**Ideal**  
STANDARD





**CERATHERM 200**  
A 5620 ..

1110 / A 866 318  
(+ A 865 612)  
Made in Germany



Ideal Standard  
 Roentgenstrasse 9  
 54516 Wittlich  
 Germany





	<b>P</b>	<b>bar</b>				<b>Q</b> (3 bar)
	<b>T</b>	<b>°C</b>				<b>l/min</b>
						<b>30</b>