








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieśe de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

1	A 963 131 NU	1 Set
4	A 963 132 NU	1 Set
8	A 963 143 NU	1 Set
9	A 963 146 NU	1 Set
10	A 963 147 NU	1 Set
14	A 960 890 NU*	1 Set
16	A 960 891 NU	1 pcs
17	A 960 706 NU	2 pcs
18	A 963 443 NU	1 pcs
20	A 960 500 NU	1 Set
21	A 963 335 NU	3 pcs
22	A 860 700 NU	1 Set
23	A 960 893 AA	1 Set
25	A 860 902 AA	1 pcs
26	A 860 897 NU	1 Set
27	A 860 204 AA	1 pcs A6765
	A 861 203 AA	1 pcs A6766
28	A 860 989 AA	1 pcs
29	A 963 309 NU	1 pcs
30	B 960 473 AA	1 pcs
31	A 861 202 AA	1 Set
32	A 960 704 NU	1 Set
	A 962 476 NU	1 Set
33	A 6677 AA	1 Set





CERAPLUS 2

A6865 .. A6866 ..







0317 / A 868 331
A865612
Made in Germany



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com





The diagram illustrates the correct use of the shower head. It shows the shower head being turned on and off, and the water temperature being adjusted. A warning icon indicates that the water temperature should not exceed 40°C.

 P	bar	 0,5	 1		 Q (3 bar)
 T	°C	 MAX. 80	 65		