









Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, GN, ...

| Pos. | Part No.     |
|------|--------------|
| 1    | A 963 131 NU |
| 4    | A 963 132 NU |
| 8    | A 963 143 NU |
| 9    | A 963 146 NU |
| 10   | A 963 147 NU |
| 14   | A 960 890 NU |
| 16   | A 960 891 NU |
| 17   | A 960 706 NU |
| 18   | A 963 443 NU |
| 20   | A 960 500 NU |
| 21   | A 963 335 NU |
| 22   | A 860 700 NU |
| 23   | A 960 893 XX |
| 25   | A 860 902XX  |
| 26   | A 860 897 NU |
| 27   | A 861 409 XX |
|      | A 861 410 XX |
| 28   | A 861 901 XX |
| 29   | A 963 309 NU |
| 30   | A 861 406 NU |
| 31   | A 861 408 XX |
| 32   | A 960 704 NU |
|      | A 962 476 NU |
| 33   | A 6677 XX    |


A 7035..  
A 7034..




Ideal Standard

**CONNECT AIR**  
**A 7034 .. A 7035 ..**

0919 / A 868 373  
(+ A 865 612)  
Made in Germany



A7034












A7035




Ideal Standard International NV  
Corporate Village - Gent Building  
Da Vincilaan 2  
1935 Zaventem  
Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)





|                  |      |      | 0    | 1    | 2    | 3    | 4    | 5    | 6  | 7    | 8    | 9    |
|------------------|------|------|------|------|------|------|------|------|----|------|------|------|
|                  |      |      | °C   | °C   | °C   | °C   | °C   | °C   | °C | °C   | °C   | °C   |
| 0,3 MPa<br>3 bar | 50°C | 16°C | 49,5 | 49,5 | 48   | 46   | 42,5 | 41   | 37 | 33,5 | 31   | 28   |
|                  | 65°C | 16°C | 65   | 65   | 63,5 | 60,5 | 57   | 53,5 | 49 | 44,5 | 39   | 34,5 |
|                  | 81°C | 16°C | 81   | 81   | 78,5 | 73   | 69   | 63,5 | 56 | 49   | 42,5 | 36   |



| P | bar | MAX. 10 | 5  | Q (3 bar) |
|---|-----|---------|----|-----------|
| T | °C  | MAX. 80 | 65 | I/min     |
|   |     |         | 40 | 23        |