






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, GN, ...

Pos.	Part No.
1	A 963 131 NU
4	A 963 132 NU
8	A 963 143 NU
9	A 963 146 NU
10	A 963 147 NU
14	A 960 890 NU
16	A 960 891 NU
17	A 960 706 NU
18	A 963 443 NU
20	A 960 500 NU
21	A 963 335 NU
22	A 860 700 NU
23	A 960 893 XX
25	A 860 902XX
26	A 860 897 NU
27	A 861 409 XX
	A 861 410 XX
28	A 861 901 XX
29	A 963 309 NU
30	A 861 406 NU
31	A 861 408 XX
32	A 960 704 NU
	A 962 476 NU
33	A 6677 XX


A 7035..  
A 7034..



Ideal Standard


**CONNECT AIR**  
A 7034 .. A 7035 ..




0919 / A 868 373  
(+ A 865 612)  
Made in Germany









Ideal Standard International NV  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)





Pressure Gauge	Thermometer	Snowflake	0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	16°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28
	65°C	16°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
	81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36



Pressure Gauge	P bar	0,5	MAX. 10	5	Thumbs up	Q (3 bar)
Thermometer	T °C		MAX. 80	65	40	Thumbs up
						l/min
						23