





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi



Position

- 1 = A 961 483 AA
- 2 = A 963 667 NU
- 3 = A 961 484 NU
- 4 = A 961 485 AA
- 5 = A 961 667 NU
- 7 = A 963 372 NU
- 8 = A 962 985 NU
- 9 = A 962 715 NU
- 11 = A 962 848 NU (2x)
- 12 = A 963 495 NU (2x)
- 15 = A 962 385 AA
- 18 = A 963 507 NU
- 19 = B 960 853 XX
- 20 = A 960 485 NU
- 22 = A 963 404 NU
- 23 = A 962 138 NU
- 24 = A 961 487 AA



Jasper Morrison
E 6405 ..







0811 / A 865 729 40
 (+ A 865 612)
 Made in Europe



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 80		65		l/min
						40		13