




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu


XX = AA, AD ...

Position

- 1 = F 960 488 XX
- 2 = F 960 425 XX
- 3 = F 960 111 XX
- 4 = F 960 695 XX
- 5 = F 960 690 XX
- 6 = F 960 251 XX
- 9 = F 960 632 NU
- 15 = F 960 056 NU (10 mm)
- F 960 057 NU (20 mm)
- F 960 058 NU (30 mm)
- F 960 059 NU (40 mm)





www.diver.com



JADO

GEOMETRY
 F 1344 ..

0811 / A 865 985
 (+ A 865 613)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com

